

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY REGION 10

1200 Sixth Avenue, Suite 900 Seattle, WA 98101-3140

OFFICE OF WATER AND WATERSHEDS

April 24, 2018

CERTIFIED MAIL-RETURN RECEIPT REQUESTED

Mr. Travis Wells, General Manager, Public Utilities Branch Warm Springs Indian Reservation PO Box C Warm Springs, Oregon 97761

Re: Sidwalter Public Water System (PWS ID #104101101) Failure to Correct Significant Deficiencies Identified by the 2014 Sanitary Survey under the Ground Water Rule and 2017 Sanitary Survey Significant Deficiencies

Dear Mr. Wells:

The purpose of this letter is to inform you of the documents contained in this package. The first document is the Environmental Protection Agency's (EPA) Notice of Violation under the Ground Water Rule for failure to correct significant deficiencies from the April 24, 2014, sanitary survey. In this letter and enclosures are the details of the violation issued, necessary actions to return the water system to compliance, public notification requirements, a template, and certification form.

The second document is the EPA's Notice of Deficiencies under the Ground Water Rule. In this letter and enclosures are the details of the deficiencies identified during the April 25, 2017, sanitary survey, the specific significant deficiencies that must be addressed, documents that must be sent to EPA, and a copy of the sanitary survey upon which our notification letter was based.

If you have any questions about the documents contained in the package, please contact Michelle Tucker at <u>tucker.michelle@epa.gov</u> or (206) 553-1414. We appreciate your efforts to protect the health of the customers of your drinking water system.

Sincerely,

Marie Jennings

Drinking Water Unit Manager

Enclosures

cc: Mr. Laddie Folster,

Tribal Utility Consultant, Indian Health Services

Mr. Roy Spino Water Manager, Confederated Tribes of Warm Springs

Mr. Russell Graham, Tribal Environmental Health, Confederated Tribes of Warm Springs

Mr. Steve Courtney, Operator, Sidwalter Community Water System

Mr. Jason Tohet, Operator, Sidwalter Wastewater Treatment Plant



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY REGION 10

1200 Sixth Avenue, Suite 900 Seattle, WA 98101-3140

> OFFICE OF WATER AND WATERSHEDS

April 24, 2018

CERTIFIED MAIL-RETURN RECEIPT REQUESTED

Mr. Travis Wells, General Manager, Public Utilities Branch Warm Springs Indian Reservation PO Box C Warm Springs, Oregon 97761

Re: Sidwalter Public Water System (PWS ID #104101101) failure to correct significant deficiencies identified by a sanitary survey under the Ground Water Rule

Dear Mr. Wells:

The purpose of this letter is to inform you that the Sidwalter Public Water System (the System) is currently in violation of the National Primary Drinking Water Regulations, specifically for failure to correct significant deficiencies under the Ground Water Rule (40 C.F.R. §141.403). The U.S. Indian Health Service, on behalf of the U.S. Environmental Protection Agency (EPA), conducted a sanitary survey on April 24, 2014. EPA notified the System of significant deficiencies on August 1, 2014. Accordingly, the owner and/or operator of the System had 120 days from the receipt of EPA's Notice of Deficiencies letter to address the significant deficiencies or submit a schedule to EPA for approval specifying how and by when the significant deficiencies would be addressed.

On November 7, 2014, EPA sent a letter reminding the system that a corrective action plan (CAP) was due by December 9, 2014. EPA received the System's request for an extension and on December 15, 2014, EPA approved a CAP for the System to address all significant deficiencies by the spring of 2015. Though some deficiencies were addressed, EPA has not received evidence that the three significant deficiencies shown below were corrected. Due to these outstanding deficiencies, the System is in violation of the Ground Water Rule. In order for the Sidwalter Public Water System to return to compliance, these remaining significant deficiencies must be corrected or placed on an approved schedule:

Uncorrected Significant Deficiencies	Corrections to be Made
Sidwalter Pump House – Sources – No	A sample tap must be provided on the well
finished sample tap	discharge pipe following treatment.
	The well vent must be screened with the
Sidwalter Well – Sources – Improper or	return bend facing downward and terminating
missing well or spring vent	18-inches above ground level or above
	minimum flood level, whichever is higher.

Sidwalter Well – Sources – Unsealed
electrical conduit at groundwater source

The conduits and junction boxes must be sealed to prevent contaminants from entering the well casing.

As a result of the violation, the Sidwalter Public Water System, as a community water system, must notify its customers of this violation within 30 days of receiving this letter and every three months afterwards until the deficiencies have been corrected. A Public Notice template, instructions, and certification are enclosed to assist you. You are also required to send a copy of the Public Notice, certification that it was issued, and an action plan to address these outstanding deficiencies to Ms. Michelle Tucker at tucker.michelle@epa.gov or:

Michelle Tucker USEPA, Region 10 (OWW-193) 1200 Sixth Ave, Suite 155 Seattle, WA 98101

In addition to the Public Notice requirements, the water system must inform its customers of any significant deficiency that is uncorrected at the time of the next consumer confidence report. The System must continue to inform the public annually until EPA determines that the particular significant deficiency is corrected.

If you have any questions about this violation or how to return your water system to compliance, please contact Michelle Tucker at <u>tucker.michelle@epa.gov</u> or (206) 553-1414. We appreciate your efforts to protect the health of the customers of your drinking water system.

Sincerely,

Marie Jennings

Drinking Water Unit Manager

Enclosures

cc: Mr. Laddie Folster,

Tribal Utility Consultant, Indian Health Services

Mr. Roy Spino
Water Manager,
Confederated Tribes of Warm Springs

Mr. Russell Graham, Tribal Environmental Health, Confederated Tribes of Warm Springs Mr. Steve Courtney, Operator, Sidwalter Community Water System

Mr. Jason Tohet, Operator, Sidwalter Wastewater Treatment Plant

Instructions for Ground Water Rule Failure to Take Corrective Action Within Required Time Frame Public Notice

Template on Reverse

A system's failure to take corrective action within the required timeframe to be in compliance with an EPA-approved corrective action plan or significant deficiency under the Ground Water Rule is a treatment technique violation and requires Tier 2 notification. You must provide public notice to persons served as soon as practical but within 30 days after you learn of the violation [40 CFR 141.203(b)]. You must issue a repeat notice every three months for as long as the violation persists.

Community systems must use one of the following methods [40 CFR 141.203(c)]:

- Hand or direct delivery
- Mail, as a separate notice or included with the bill

Noncommunity systems must use one of the following methods [40 CFR 141.203(c)]:

- Posting in conspicuous locations
- Hand delivery
- Mail

In addition, both community and noncommunity systems must use *another* method reasonably calculated to reach others if they would not be reached by the first method [40 CFR 141.203(c)]. Such methods could include newspapers, e-mail, or delivery to community organizations. If you mail, post, or hand deliver, print your notice on your system's letterhead if available.

The notice on the reverse is appropriate for mailing, posting, or hand delivery. If you modify this notice, you must still include all required Public Notice elements from 40 CFR 141.205(a) and leave the mandatory language unchanged (see below).

Mandatory Language

Mandatory language on health effects, which must be included as written (with blanks filled in), is presented in italics in each notice with an asterisk on either end.

You must also include the following italicized language in all notices, where applicable [40 CFR 141.205(d)]. Use of this language does not relieve you of your obligation to take steps reasonably calculated to notify all persons served:

Please share this information with all the other people who drink this water, especially those who may not have received this notice directly (for example, people in apartments, nursing homes, schools, and businesses). You can do this by posting this notice in a public place or distributing copies by hand or mail.

Corrective Action

In your notice, describe corrective actions you are taking. Listed below are some steps commonly taken by water systems with Ground Water Rule treatment technique violations. Depending on the corrective action you are taking, you can use one or more of the following statements, if appropriate, or develop your own text:

- Although we did not meet our deadline, we are now in consultation with EPA to develop a corrective action plan.
- The [source of contamination/significant deficiency] has been identified and addressed.
- We have implemented a short term plan to address the immediate issue while we pursue the long-term solution.

Repeat Notices

For repeat notices, you should state how long the violation has been ongoing and remind consumers of when you sent out any previous notices. If you are making progress with correcting the significant deficiency or addressing the fecal indicator-positive source sample, describe it. Alternatively, if funding or other issues are delaying corrective action, let consumers know.

After Issuing the Notice

Make sure to send your primacy agency a copy of each type of notice and a certification that you have met all public notification requirements within ten days after issuing the notice [40 CFR 141.31(d)].

Ground Water Rule Failure to Take Corrective Action Within Required Time Frame Public Notice

IMPORTANT INFORMATION ABOUT YOUR DRINKING WATER

[System] Failed to Correct a Significant Deficiency Within Required Time Frame.

Our water system recently violated a drinking water requirement. Although this incident was not an emergency, as our customers, you have a right to know what happened and what we did (are doing) to correct this situation.

A routine inspection conducted on [give date] by the US Indian Health Service on behalf of the US Environmental Protection Agency (EPA) found [describe significant deficiency in our water system]

As required by EPA's Ground Water Rule, we were required to take action to [correct this deficiency]. However, we failed to take this action by the deadline established by EPA.

What should I do?

- There is nothing you need to do. You do not need to boil your water or take other corrective actions. However, if you have specific health concerns, consult your doctor.
- If you have a severely compromised immune system, have an infant, are pregnant, or are elderly, you may be at increased risk and should seek advice from your health care providers about drinking this water. General guidelines on ways to lessen the risk of infection by microbes are available from EPA's Safe Drinking Water Hotline at 1-800-426-4791.

What does this mean?

This is not an emergency. If it had been, you would have been notified within 24 hours.

Inadequately treated or inadequately protected water may contain disease-causing organisms. These organisms include bacteria, viruses, and parasites which can cause symptoms such as nausea, cramps, diarrhea, and associated headaches.

These symptoms, however, are not caused only by organisms in drinking water, but also by other factors. If you experience any of these symptoms and they persist, you may want to seek medical advice.

What is being done?

[Describe corrective action.] We anticipate resolving the problem within [estimated time frame] (or the problem was resolved on [give date]).

For more information, please contact [name of contact] at [phone number] or [mailing address].

Please share this information with all the other people who drink this water, especially those who may not have received this notice directly (for example, people in apartments, nursing homes, schools, and businesses). You can do this by posting this notice in a public place or distributing copies by hand or mail.

This	notice is	s being	sent to	you by	[system].	State	Water	System	ID#:	
Date	distribu	ted:								

Public Notification Certification The water system must complete this selements.		ure below cer	rtifies that the notice contains all required
Complete the following items (ch	eck all that app	ly):	
		-	of receiving EPA's Notice of Violation for survey under the Ground Water Rule.
(For non-community systems Of within 30 days of receiving EPA's Noby a sanitary survey under the Grounds	otice of Violation	d at 1 for failure t	on/on/
All systems - Provide information of a method. Such methods could include a			ners if they would not be reached by the first ommunity organizations, etc.
Water System		PWS ID	
Signature of owner or operator	Position		Date
Send a copy of the completed notice (OWW-193), 1200 Sixth Ave, Suite			tucker.michelle@epa.gov or US EPA R10



Signature

Corrective Action Plan

EPA Region 10

Tribal Public Water System Supervision Program

All public water systems are required to undergo sanitary surveys. Public water systems using groundwater water must consult about required corrective actions within 30 days of being notified of a significant deficiency and must complete corrective actions or be in compliance with an approved Corrective Action Plan within 120 days of receiving notice of significant deficiencies (40 CFR 141.403 (a)).

A proposed corrective action plan must provide a written description of <u>how</u> and <u>on what schedule/when</u> the following significant deficiencies will be/were addressed. Please fill in the table below and submit documentation of correction to the significant deficiencies below to Michelle Tucker at <u>tucker.michelle@epa.gov</u>. Please submit photos, receipts, or other items documenting corrections that have been made (reference documentation with written statement in column B).

1		
CWS		
ater		
4		
eck		
4/24/2018		
Schedule to Address Deficiency		Accomplishments
Milestone/Corrective Action Description	Scheduled Date	(date completed)

ided with this plan:		
oproved Deficiency Corrective Action Plan may constitute address	a violation of the	e Safe Drinking
email		
	email	email

Date

Deficiency	Schedule to Address Defic	iency	Accomplishments
Deficiency	Milestone/Corrective Action Description	Scheduled Date	(date completed)
	EPA Use Only		
			500000000000000000000000000000000000000
approved by (print)		-	closed date
			_
	Compliance Officer Signature	Date	



Indian Health Service Portland Area Office 1414 NW Northup St, Suite 800 Portland, OR 97209

09 May 2014

Don Courtney Public Works General Manager Confederated Tribes of Warm Springs P.O. Box 1196 Warm Springs, OR 97731

Dear Mr. Courtney:

Thank you for the time of your operator to complete the site visit of the Sidwalter community water system (PWSID: 1041011101). The assessment of the water systems is a tool for identifying areas requiring improvement, and maintenance. Enclosed is the water system sanitary survey report conducted on April 24, 2014 and is a snapshot of the systems on that day.

Significant Deficiencies and Recommendations

1. Page 2 of 8, item 1

The well is in need of a sanitary cap equipped with a vent and a proper seal (see figure 1). Installation of a sanitary well cap with a rubber seal and vermin barrier will ensure public health is protected by providing a barrier to contamination and water intrusion into the well.




Figure 1

2. Page 2 of 8, item 4

There is no post-treatment sample tap available (see figure 2). Installation of a post-treatment sample tap will allow for measurement of disinfection levels prior to distribution to the system and will help operators ensure proper levels of disinfectant are being dosed.




Figure 2

3. Page 2 of 8, item 6

The well vent is not sealed, screened, and turned down (see figure 3). Installation of a vent that is sealed, screened, and turned down ensures public health is protected by providing a barrier to pests and water intrusion into the well and water supply.




Figure 3

4. Page 2 of 8, item 7

The wiring leading into the well in not encased in conduit or sealed to the well cap (see figure 4). Providing a seal and proper conduit will ensure the well and water supply remain free from contamination.




Figure 4

5. Page 7 of 8, item 235

The system lacks a pressure relief valve or surge arrestor in the pumphouse. The system experiences a water hammer and flow back through the water meter (figure 5). A water hammer poses a threat to the safety of the operator and structural integrity of the water system. Installation of a pressure relief valve or surge arrestor to absorb the water hammer will ensure the safety of the operator and integrity of the system are maintained.




Figure 5

Minor Deficiencies and Recommendations

6. Page 2 of 8, item 19

The well cannot be pumped to waste at capacity at a location prior to the first connection. Design that allows pumping to waste is recommended for collection of source water and investigative samples.

7. Page 2 of 8, item 20

Standby or auxiliary power are not available. The addition of auxiliary power ensures a safe supply of water remains sufficient during times of emergency or power failure.

8. Page 3 of 8, item 57

The chemical feeders are not flow paced. Controlling of chemical feeders through a flow-sensing device ensures an accurate injection of chemicals into the system based on the flow of water from the well. Currently the system is arranged so that the well pump provides a constant amount of flow, which the chemical feed pumps is adjusted to.

9. Page 3 of 8, item 63

The system is lacking an eye-washing device. Installation of an eye-washing device or portable eye-washing bottles is an important safety measure to ensure employee health and safety is maintained.

10. Page 4 of 8, item 122

The system does not have a program in place for regular exercise of valves. Regular exercise of valves ensures proper operation and helps identify areas in need of repair and maintenance.

11. Page 5 of 8, item 146

The gate to the storage tank area is locked from unauthorized entry, however the ladder to the tank is unsecured. Ensuring security on the tank ladder is maintained precludes unauthorized access to the storage tank, and ensures the structure remains free from vandalism and contamination.

12. Page 7 of 8, item 218

There is no current wellhead protection program in place. Establishment of a well head protection program will ensure the highest quality of water is maintained by preventing contaminants from reaching drinking water sources.

The water system received violations for consumer confidence reports (CCR) in 2011, 2012, and 2013. These reports were not received by EPA before the July 1st annual deadline. These violations have since been returned to compliance status. To prevent future violations, ensure CCRs are sent to system customers and EPA annually by July 1st, and the CCR certification form is sent to the EPA no later than October 1 annually.

Feel free to call me at (503)-414-7786 with any questions, comments, or concerns regarding the assessment details. A copy of this report will be sent to Region X Federal Environmental Protection Agency (EPA) Drinking Water Program, and any remarks received from the Confederated Tribes of Warm Springs will be forwarded to the EPA.

Sincerely,

Tia Skerbeck Indian Health Service Tribal Utility Consultant

Enclosure

Cc: Roy Spino, Water/Wastewater Engineer, Confederated Tribes of Warm Springs

Lisa Jacobsen, Tribal Drinking Water Coordinator, Environmental Protection Agency

Steve Anderson, District Utility Consultant, Indian Health Service

Matt Rasmusson, District Engineer, Indian Health Service Jason Davis, Environmental Engineer, Indian Health Service

Nancy Collins, Environmental Health Officer, Indian Health Service

	NOIL Y YOURNI LISIA JALIS			SURVEY DATE	PWS ID
	I MATCHANIAN I			F 7 0 3	-
Sanitary Survey includes: (1) Water Sources: (Check all that applies) (5) Pumps, Pump F	Ground Controls	Surface (2) Well Water Treatment: (6) Monitoring	(3) Ranagement/Operation Capacity	Distribution (8) Operator Compliance	(4) Finished Water Storage (4)
Date of last survey System Type: 05/04/2014	Federal Government \Box Private \Box	State Government Native American Government	Local Mixed (Public/Private) Other	rivate) District SouthenCascade	TOTOTAL ALCOARDING TO THE TOTOTAL ALCOARDING TOTOTAL ALCOARDING TO THE
# of Residential Connections #	# of Non-Residential Connections	# of Population ~120-135	# of Storage Facilities	# of Ground Source	# of Surface water Source V/A
Name of Water Supply		Water Purchased From: Name N/A	PWS	NO NO	
Sidwalter CWS	(0	Water Sold To:	PWS	Type: Well field I,ake □ Infiltration Gallery □ Other □	River/stream []
Address			Owner Name Confederated Tribes of Warm Springs	arm Springs	
Mailing Address	THE CONTRACTOR OF THE CONTRACT		Owner Address 1233 Veterans St		
City, State and Zip Code	Telephone		City, State and Zip Code Warm Springs, OR 97761	Telephone 541-553-1161	
Plant Location (if different than mailing address)	g address)		• WERE STRUCTURAL DEF YES \(\text{T} \) NO \(\text{T} \)	WERE STRUCTURAL DEFICIENCIES NOTED DURING THIS SURVEY YES □ NO □ IF YES, SEE PAGE(S)	VEY.
System Manager's Last Name: Spino			Individual present during inspection: Tia Skorbock	두 -	
System Manager's First Name: Roy			Name: Tid Oner Decor	Title: IHS Engineer	A CONTRACTOR OF THE PROPERTY O
System Manager's Address: P.O. Box C/Water Engineer	System Manager's City: Warm Springs	er's City; ngs	Name: Nancy Collins	Title: Sanitarian	翌日
System Manager's State: OR	System Manager's T 541-553-2324	System Manager's Telephone Number: 541-553-2324	Name RoySpino Steven	CTOVENCIAL Tritle: Watermanager (ser (a.Dh
			Water System Classification Service Category Community Water System	sicat Non-community	Transient Non-community
		1997	Surveyors Agency Indian Health Service	alth Service	Ammerym (Color and Color and Address of Color and Address of Color and Color
Comments:					
Surveyed by Tia Skerbeck 4/24/2014	Date Received by	varse 4.24.14			
WHITE - WATER SYSTEM YELLOW - EPA	COW - EPA PINK - IHS	Rev. 03 24 2011 Official Form SS 1	SS 1 Keep For Your File		Page of &

SURVEY DATE PWS ID 0 4 2 4 2 0 1 4 1 0 4 1 0	ource Type: round water non-purc	Water Sold to N/A			3,000	51 Grout Dept (Ft) 25 Date Drilled 985	Section 12 Se Quarter/Quarter	of this area? If yes, is this for all water sources? UNKNOWN VES NO UNKNOWN UNKNOWN	Are chemical contaminants source in sanitary control area? YES NO UNKNOWN	MINOR DEFICIENCY		namained and operating property? Is well site properly drained and protected from unauthorized entry?	. Is well site protected against flooding?	Can the well be pumped to waste at the design capacity of the well via		Is a pressure gauge or other means of measuring water level provided at the installation and is it maintained and working properly?		- COLOMBIA - AND	RECOMMENDATION	WELL HOLISE BUILDINGS CONSTRUCTED OR MAINTAINED TO DROWNE.	Lighting	Venting No storage of toxic/hazard chemical.		Protection from rodent infestation.		Page 2 of 8
	Status: Active II Inactive Proposed	Water Purchased from N/A	Treatment Methods Sodium hypochlorite		Design Daily Production (GPD) 20,000	504 350-400, 400-451	1sh	Is there a Well Head Protection Plan of this area? YES [] NO (Are static and pumping water levels measured regularly? YES UNKNOWN		YES NO NA UNK	X 0 0 0 17.) (i	Z 0 0 29.	0 0 21.			TO STATE OF THE PROPERTY OF TH	D D D 22.					Comments:	SS2 Keep For Your File
SHOGLIOS GREV MUNICORS	Source Name: Sidwalter/Well	Physical Address no formal address avail Start End	Treatment Objective Disinfection	Has well-log been submitted to EPA? YES [] NO [] (UNKNOWN J	Pump Capacity (GPM)	Casing Depth (Ft) 487 Interval Screen Depth (Ft) 248-	658 Meridian	Unknown 🗆 🔏		SIGNIFICANT DEFICIENCY	YES NO NA UNK C) A C 1. Is the well provided with a sanitary cap, vent and seal that are properly	installed? 2. Does the easing extend a min. of 18 inches above the final ground	surface and/or 12 inches above the pump house floor or slab? I litter a sample tap provided on the well discharge pipe prigr to	L A. Is there a sample provided on the well discharge pipe following	5. Is the well cased and grout sealed at least 20 feet or in such a manner	that surface water cannot enter the well? 6. Is well vent screened with the return bend facing downward and terminaring 18 inches above ground level or above maximum flood	ievel, whichever is higher?	entering the well casing?	HAVE THE FOLLOWING MIN SET-BACK FROM THE PWS WELL BEEN MET?	C C C Gravity sewer line (100 ft)		C C T T L Livestock (100 ft)	D D 14. Individual home scepage pit (100 ft)	☐ ☐ IS. Has a GWUDI determination been done for this source? If yes, is it filtered ☐ or unfiltered ☐	Surveyed by Date Received by Date Tia Skerbeck 4/24/2014	1 77

SURVEY DATE 0 4 2 4 2 0 1 4 1 0 1 1 0 1		☐ A ☐ 122. Are valves periodically exercised?	☐ 123. Are customer complaints and investigation reports kept?	☐ ☐ ☐ X 124. Are all automatic air relief valves equipped with a means of backflow	☐ ☐ ★ ☐ 125. Are ARV's timed down, screened and protected from cross	☐ X ☐ ☐ 126. Is there a routine main and dead-end water flushing program?	Are backflow prevention devices installed at all appropriate locations?		0		RECOMMENDATION		□ □ □ 131. Is there a leak detection program?	☐ ★ ☐ 132. Are all service metered and are meters routinely goad?	□ ∯ □ □ 133. Was asbestos/cement pipe used in the system?								6 Keep For Your File Page 4 of 8
3. DISTRIBUTION What type of material are the pipe(s): PVC V AC D PE V CVDI D	Service Lines (Diameter and type)	2. 2.	How many services are metered Number of Fire Hydrants (types if known)	36 out of 36 1. 2	.:		SIGNIFICANT DEFICIENCY	YES NO CAN UNK	•	.	0 0 114,	O O 115.	distribution system: 116. Are proper residual test kits available and well stocked with reagents		throughout the distribution system (including fire flow)? □ □ 118. Is the system protected from obvious cross connection observed during the survey?	□ □ ₩ □ 119. Is there a requirement for annual testing of the installed backflow	prevention devices?	Comments:				Surveyed by Date Received by Date Tia Skerbeck 4/24/2014	WHITE - WATER SYSTEM YELLOW - EPA PINK - IHS Rev. 03 24 2011 Official Form SS 6

44.8832 -107 121.48145 -10ng

PORTLAND AREA INDIAN HEALTH SERVICE PUBLIC WATER SYSTEM SANITARY SURVEY

PUBLIC WATER SYSTEM SANITARY SURVEY STRVEY DATE PWS.ID	Total Storage Capacity (gals) 209,000 gal	on of storage structure Pressure tank name Physical location of storage structure	Storage type Stand pipe Type of hydropneumatic system: Non-Bladder 🗆 Bladder 🗅	steel Volume (gal): 209,000 Date in service: Type of material Volume (gal)	Cleaned Inspected Total design capacity Date last: Cleaned Inspected	YES NO NA UNK		inspector?	_ \ :	Are access many percentage for the storage structure 4 inches or greater above the reservoir roof surface, with a lid 2 inches overlanping. water tight and locked?	Are overflow lines, air vents, drainage lines or clean out pipe turned downward or covered, screened and terminated a minimum of 2 times the diameter of the water outlet above the ground or	ENCY MINOR DEFICIENCY	ilisaan naa dina aa maadaa aa daadaa aa aa daadaa aa aa daadaa	system for repairs or	 Do all vents open downward and are they fitted with a 4 mesh non-	the past 5 years? 161. Do all non-bladder hydro pneufnatic tank(s) have the following? If VFS which one: Works eight olses [] A drain	Means to add air Automatic or manual air blow-off Antomatic or manual air blow-off An access manhole (24 inches diameter where practical)				149. Is there a water-sampling tap provided at the storage structure	When was the storage structure inspected last? How often is the storage structure cleaned? Ined? Line Type?	
Suot	FINISHED WATER STORAGE	Physical location of storage structure		Type of material: Bolted steel	Date last: Cleaned	134. Is treated water storage covered or enclosed?	L.S. IS the storage structure clean and tree from comamination:	 Is the storage structure structurally sound? Is the storage structure safely accessible to inspector? 				MINOR DEFICIENCY			5. Do all vents open downward and are	corrodible screen? Is the storage structure secured from unauthorized access?		147. Does the overflow have a splash pad?	3. Is there a separate drain line on the storage structure?	RECOMMENDATION	J. Is there a water-sampling tap provide	Never 150. Never 151. Is storage structure	TO THE
Suot - Station	4. FINISH	Storage structure name Sidwalter	Type of corrosion control Cathodic	L			ם כ			□ 💢 139.	□ □ 140.			(🗆	 □ ¥ 145.	O 0 146.			MARCHARA			rs	
2	7	Storage structure	Type of corrosio.	Date in service:	Total days of supply	2 o c) (_ 		4 .c	0	 _ _ _	爱		o)	X	Way the transfer of the transf	7	≤1 yr	

Keep For Your File

Official Form SS 7

WHITE - WATER SYSTEM YELLOW - EPA PINK - IHS

	ON K UNK UNK 183 184 197 197 198 198 198 198 198 198	Significanter CWS Significant DeFiciency	tration) the? ion of maximum residence time? on of maximum residence time?	Are the following records main YES NO NA UNK YES OF THE COLUMN OF THE CO	Are the following records maintained on-site or location nearby? YES NO NA UNK 203. Bacteriological Analysis 204. Chemical Analysis 205. Copies of past sanitary survey 206. Copies of past sanitary survey 207. Reports of variance or exemption 208. Copies of public notices 210. Are daily free/total chlorine residual taken?	cu;
Surveyed by Fia Skerbeck 4/24/2014	× 4/2,	Date Received by 1/2014	Date			
		1 km < 1		ALLES AND THE STATE OF THE STAT		

PWS ID 1 0 4 1 0 1 1 0 1			Meets System Date Date Requirements Issued Expires		16S 20M		nriate leve!?		able at all times?			D	achs thessure reliet without Spyloke cooter hammer		THE THE RESERVE A LABOR TO THE PARTY OF THE	The state of the s							Page 7 of 8
SURVEY DATE 0 4 2 4 2 0 1 4	OR COMPLIAN	SIGNIFICANT DEFIGIENCY	t, Cert.	R Dist 1	CUBING		233. Are Operators certified at the appropriate leve??	MINOR DEFICIENCY	234. Is a properly certified operator available at all times?	OTHER	SIGNIFICANT DEFICIENCY	The state of the s	25 COC 10 COC 15	236.	237.		430.	239.	240.	makakanaka manana m		Comments: 219. CCR VIOLATIONS FOIL 2011, 2012, 2013	Ле
	%	SIGNIF	岗	Roy Spino	Steven Gavengor		YES NO NA UNK			9. OT		S NO NA UNK			Administrative (Conference and Conference and Confe]]			Control Contro		Comments: 219. CCR VIOLATIONS fo	n SS 10 Keep For Your File
	X.		n to his termina poor	intenance manual?	otocol for other	plan?	Control Program?		TOTAL POST IN O YEARS	n Program?	ar?	Market Service Construction	ilan?	n/program	-	o officers	entory?	directors?	nong the people Water System?	ver? Transfer switch only Other	□ Infrequently	Date	24 2011 Official Form SS 10
	ERATION CAPAC	DEFICIENCY	certified at appropriate level?	System have an operation and mai	s have written standard operating pa	system have an emergency response	System have Cross-Connection Con	TOTENCY	ystem in compliance? CCK W	r System have a Wellhead Protection	confidence report sent to user each ye	r System have a current mater plan?	r plan include a water conservation p s the master plan completed?	en Water Quality Monitoring site pla	NDATION	rr System have an Operating Budget	a System have a water facilities inv	assessment been completed? have a governing body or board of	plan of organization and coutrol are management and operation of the	r System have emergency power? automatic switchover Transf manual switchover Other	ith transfer switch esting generator: □ Quarterly □ Annually	Received by	PINK – IHS Rev. 03 24 2011
	NAGEMENT/OPERATION CAPACI	SIGNIFICANT DEFICIENCY	211. Is the Manager certified at appropriate level?	212. Does the Water System have an operation and maintenance manual?	213. Does the system have written standard operating protocol for other operators?	214. Does the water system have an emergency response plan?	☐ 215. Does the Water System have Cross-Connection Con	MINOR DEFICIENCY	216. Is the Water System in compliance? (CC) COO 217. Does the system have more than 4 violations in the past two years	218	☐ 219. Are consumer confidence report sent to user each year?	220.	 221. Does the mater plan include a water conservation plan? 222. What year was the master plan completed? 19 	there a writte	RECOMMENDATION	☐ 224. Does the Water System have an Operating Budget? ☐ 224. Does the Water System have a service area and Socility man?	226.	☐ 227. Has a capacity assessment been completed? ☐ 228. Does the PWS have a governing body or board of directors?	229.	es the Water System have emergency pov Generator, automatic switchover	Portable with transfer switch 231. Frequency of testing generator: □ Monthly □ Quarterly □ □ Never	Date Received by A/24/2014	YELLOW - EPA PINK - IHS
	7. MANAGEMENT/OPERATION CAPACI	SIGNIFICANT DEFICIENCY		212. Does the Water System have an operation and mar	213. Does the system have written standard operating ps operators?	214. Does the water system have an emergency response	215. Does the Water System have Cross-Connection	MINOR DEFICIENCY	216. Is the Water System in compliance? CTT. 217. Does the system have more than 4 violations i	218	219.	220.	221.	223.	RECOMMENDATION	224.	226.	227.	□ 229.	230. Does the Water System have emergency pov C Generator, automatic switchover C C Generator, manual switchover C	Portable with transfer switch Frequency of testing generator: □ Monthly □ Quarterly □ □ Never	Date	PINK – IHS

	and all the same of the same o			.		CONTRACTOR A	to a constant			-						1	haven		*vecessor*				- Company									
	relya, wychon					enterioretten sta	Consideration (agency																									ŷ
				İ		te between carries on 17	i maniana i												a.com.euro													
						Validated	****																									0
		er ver meer ver												-					OR LOCATION													٥
			70.00			Sanakarran	and a second			-		******				enten iin Serge			****													
						an water or the		a a constant a constan																						ormana.		
J				alam Ashan Ma		***************************************			and proportion			1-2-100 ·													-,,-		-1,-1,1,4				minimos	
-		A STATE OF THE STA		. acacuman		}																		-								
		a per di mana		DATE COMPANY	and the second																				_							
- ALIEN		a constant		Manage Cont.					THE PERSON	1																						
NA CASA				- Annual Marie	2			2	BA I O MARGINA AN	}						-		***********														
Laurana and				200.ccc.mm10	na ra reduced				700 1000	į																						
	MACHINIAN .			CASIC SECURITY OF THE PARTY OF	-				A WORLD TAPE OF THE SECOND																					,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		
Northwart contract	and the same			- Commission of the Control of the C			and Observation to									-				\dashv						************						
A CATALON TO THE REAL A.	Particulation of the Vil				1	-	010000			La Company		r		ones ones for		norman de la composición dela composición de la composición de la composición dela composición dela composición dela composición de la composición dela				en andresse rum i Pro												
Consessed of	and many assessment					A ELABORET	Technology (İ	WITH BROWN A.						1	-															
-						Managana A.	and the second second			PRODUCTOR BANKS					Toposon i descrito			,														
	winsessess						con any inches department			POPULATION PROPERTY.					The state of the s		-															
٠	***************************************				*	our phase in the	and the second			annammen.					-									on the same	***************************************		manifes entro		anti A Lake Lake and			
	consequent bearings				ì	T. T. S.			ļ	A															THEORET	encores m	non vennous			. Effectively and		
	***************************************			İ		Anoques s reve		Å	į	AND AND AND AND AND AND AND AND AND AND																						
	Page Value of the Control of the Con								THE STATE OF THE S	Commany of France																				·		
Ì	Mary navagany (s						-		1	903980503																						
	MICHAEL SALVERS					*****	Seat No.	u u umanoo	f				~~~		~~~	······································		******					_									
	o sida o rayer				İ	anno anno	Section and	ora resorman		74.81.44.444.4.4.4.4.4.4.4.4.4.4.4.4.4.4.	· ·																				-,,	
	1					100 M 101 M 101 M		e-customan												~~~	F77111 V 1180					al-attentivat						
						CAMA LANGERON	4.00	A. A. J. J. S. S. S. S. S. S. S. S. S. S. S. S. S.	}	olice and annual																				,		İ
		e of characteristics		į	1 BUILDING BUILDING		4).	*****		- interesting		an a same			- Indiana							II naukusellanan	a haad ad basada had aad							
	}	WILLIAM I PARKET			Mary Constitution	***************************************		W.C.L.	and the second		CHARLES AND ADDRESS OF THE PARTY OF THE PART																	***************************************				
-		A Volument			Thomas or the				an community and a second		***************************************													*********	ur Arada	annan na r	contrate the contrate of			**********	Cardinals (Conde	
		eranomi (en			ADDRESS CO				mannama		-															od Cit Estato.				***************************************		
	}	CONTRACT THE CONTRACT						OTHER DATE OF THE OWNER OWNER OW	amanan man		appropriate the second									-					en en en en	mmanin		nmreevor	····	OMETICAL STATE		
		-						of company					-						***************************************													
					And Proced Acoustin			d'ann airtean	TRANSPORT VALUE																		-,			,		
		en residente de la composition della composition della composition della composition della composition della composition della composition della composition della composition della composition della composition della composition della composition della composition della composition della composition della composition della composition della composition della composition			STATE OF THE PARTY OF			accompanies and	PARK SAME										-									**				
	ļ.	n American			P. P. P. P. P. C.							handler of the officer	o de como no caso de		/ Palatinima - I P - 1	Anna ann ann an Anna																
		Paralli Salvania			DIACON NAMED OF			Ì											***************************************	200.1000												
		PH 174007000			Total Contrast				or received										or 1 comments													
		e avoir a a a a a a a a a a a a a a a a a a a			ACOUNT MATOR				an an an													·										
		TO THE PARTY OF TH			and the second				0.000																	v.w						
No. of Concession, Name of Street, or other Desires.		Total Part Company		1	Courties to Colouries	***************************************			Section (Section)																*********	·******		mrmaamini		v.m	/	
ad toutaness areas		-			A CANADA CANADA SA SA SA SA SA SA SA SA SA SA SA SA SA				***************************************																					·		
-		***************************************			No. Read Read Property.						-																					i.
er manus made		7			COLUMN AND REAL COLUMN				W. Marie Constitution of the Constitution of t											A STATE OF THE PARTY OF THE PAR												
22.00		T E C PROTECTION			er/septonosis					-								~11.00V.a.~~														
		***************************************			A TO STATE OF THE				J. P. J. L. P. J. P. J. L. P. J. P. J. L. P. J. L. P. J.																							Į
	1	200 PER 000 PE		-	ALL AND DESCRIPTION AND	1			AND MARKET THE PARKET AND ADDRESS OF THE PAR		As a shirthdataland										\dashv											
		Personal Property			Acres de la Bassa				ALL STREET, ST	***************************************																-4.						
İ	į.	***************************************		4	and the	-	f	1	-	ł		[]					1		l							L	L					



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY REGION 10

1200 Sixth Avenue, Suite 900 Seattle, WA 98101-3140

> OFFICE OF WATER AND WATERSHEDS

April 24, 2018

CERTIFIED MAIL-RETURN RECEIPT REQUESTED

Mr. Travis Wells, General Manager, Public Utilities Branch Warm Springs Indian Reservation PO Box C Warm Springs, Oregon 97761

Re: Sanitary Survey Significant Deficiencies at the Sidwalter Community Water System, PWS ID #104101101

Dear Mr. Wells:

Thank you for having your sanitary survey conducted by Indian Health Service's tribal utility consultant Laddie Folster on April 25, 2017. A Sanitary Survey is a comprehensive evaluation of the source, pumps and pumping facilities, treatment, storage, distribution, laboratory facilities, management and operator qualifications at a public water system, required under the National Primary Drinking Water Regulations (40 CFR Part 141). This letter is to inform you that significant deficiencies were identified at the Sidwalter Community Water System during the sanitary survey.

These significant deficiencies have the potential to impair your water quality and jeopardize public health. Significant deficiencies require immediate attention and must be corrected within 120 days from receipt of this letter. If you are not able to address significant deficiencies by this deadline, you must be on an approved corrective action plan. Failure to do so will result in a violation of the National Primary Drinking Water Regulations (40 CFR §141.403).

Due to the failure of the Sidwalter Water System to correct significant deficiencies from the prior sanitary survey, a violation has already been issued under the Ground Water Rule. Those significant deficiencies are reiterated here as they were still not corrected at the time of the most recent survey; the process for bringing the system back into compliance is detailed in the enclosed Notice of Violation letter. The remainder of this letter addresses actions the Santiago Water System must undertake in response to the newest sanitary survey conducted on May 23, 2017.

<u>Significant Deficiencies</u>: The following items must be corrected, or on an approved schedule to be corrected, within 120 days of receipt of this letter for ground water systems or another violation will be issued.

- #4 A sample tap is not provided on the well discharge pipe following treatment.
- #6 The well vent is not screened with the return bend facing downward and terminating 18-inches above ground level or above minimum flood level, whichever is higher.

• #7 Conduits and junction boxes are not sealed to prevent contaminants from entering the well casing.

<u>Minor Deficiencies</u>: The following items should be corrected prior to the next sanitary survey so that they do not become significant deficiencies in the future.

- #19 The well cannot be pumped to waste at the design capacity of the well via an approved air gap at a location prior to the first service connection.
- #20 Standby or auxiliary power is not available.
- #63 There is not a deluge shower and/or eye washing device installed where strong acids and/or alkalis are used or stored.
- #120 Valves are not periodically exercised.
- #121 Customer complaints and investigation reports are not kept.
- #124 There is not a routine main and dead-end water flushing program.
- #126 The operator is not trained in cross connection control.
- #146 There is not a separate drain line on the storage structure.
- #165 All non-sample taps installed in the pump house are not equipped with an appropriate backflow prevention device.
- #216 The Water System does not have a Wellhead Protection Program.
- #217 Consumer confidence reports are not sent to users each year.
- #218 The Water System does not have a current master plan.
- #219 The master plan does not include a water conservation plan.

<u>Recommendations</u>: The following items are best management practices shown to improve drinking water systems; addressing these items is voluntary.

- #27 Well house buildings are not being maintained to provide protection from rodent infestation.
- #129 There is not a leak detection program.
- #130 All services are not metered and/or meters routinely read.
- #147 There is no water-sampling tap provided at the storage structure outlet.
- #175 There is no water pressure relief valve installed where the pump is directly connected to the distribution system.
- #225 A capacity assessment has not been completed.
- #228 The Water System does not have emergency power.

The Ground Water Rule requires systems to consult within 30 days of receiving a notice of a significant deficiency. Significant deficiencies require immediate attention and must be corrected within 120 days from receipt of this letter. If you are not able to address significant deficiencies by this deadline, you must be on an approved corrective action plan. Documentation of significant deficiency corrections made, and/or a schedule of the dates and actions of future corrections, must be submitted to tucker.michelle@epa.gov within the 120 day deadline or violations will be issued.

If you have any questions or would like to address the findings of the sanitary survey, please feel free to contact me at tucker.michelle@epa.gov or (206) 553-1414. We would like thank you and

your staff for their cooperation and time on the survey as well as assistance in addressing these findings.

Sincerely,

Michelle Tucker

Michelle Tucker Ground Water Rule Manager

Enclosures

cc: Mr. Laddie Folster,

Tribal Utility Consultant, Indian Health Services

Mr. Roy Spino Water Manager, Confederated Tribes of Warm Springs

Mr. Russell Graham, Tribal Environmental Health, Confederated Tribes of Warm Springs

Mr. Steve Courtney, Operator, Sidwalter Community Water System

Mr. Jason Tohet, Operator, Sidwalter Wastewater Treatment Plant



Corrective Action Plan

EPA Region 10

Tribal Public Water System Supervision Program

All public water systems are required to undergo sanitary surveys. Public water systems using groundwater water must consult about required corrective actions within 30 days of being notified of a significant deficiency and must complete corrective actions or be in compliance with an approved Corrective Action Plan within 120 days of receiving notice of significant deficiencies (40 CFR 141.403 (a)).

A proposed corrective action plan must provide a written description of <u>how</u> and <u>on what schedule/when</u> the following significant deficiencies will be/were addressed. Please fill in the table below and submit this proposed corrective action plan within 120 days to Michelle Tucker at <u>tucker.michelle@epa.gov</u>. Please submit photos, receipts, or other items documenting corrections that have already been made (reference documentation with written statement in column B).

PWSID:	104101101		
System Name:			
Primary Source:			
Sanitary Survey Date:			
Surveyor:	Laddie Folster		
Notice Date:	4/24/2018		
Corrective Action Plan Due Date:	9/22/2019		
Deficiency	Schedule to Address Deficiency	000000000000000000000000000000000000000	Accomplishments
Deficiency	Milestone/Corrective Action Description	Scheduled Date	(date completed)
Sources - #4 Is there a sample tap provided on the well discharge pipe following treatment			
Sources - #6 Is well vent screened with the return bend facing downward and terminating 18-inches above ground level or above minimum flood level, whichever is higher			
Sources - #7 Are conduits and junction boxes sealed to prevent contaminants from entering the well casing			
Please list any additional attachn	nents included with this plan:		
I understand that failing to meet Water Act.	an EPA approved Deficiency Corrective Action Plan may constitute	a violation of the	e Safe Drinking
Name (print)	address		
Phone	email		

Deficiency	Schedule to Address Deficiency		Accomplishments
Deficiency	Milestone/Corrective Action Description	Scheduled Date	(date completed)
Signature		Date	-
	EPA Use Only		
	EPA OSE OHLY		
approved by (print)	_		closed date
approved by (print)			ciosed date
	Compliance Officer Signature	Date	~



Indian Health Service Spokane District Office 528 E Spokane Falls Blvd., Ste 302 Spokane, WA, 99202

June 1, 2017

Roy Spino Water Manager Confederated Tribes of Warm Springs PO Box 1209 Warm Springs, OR 97761

Dear Don:

Thank you for the time and assistance from Jason Tohet in completing the sanitary survey of the Sidwalter Community Water System (PWSID 104101101), conducted on 4/25/2017 by the Indian Health Service (IHS). The assessment of the water system is a tool for identifying areas requiring improvement and maintenance, and must be conducted every three years in accordance with the Safe Drinking Water Act (SDWA). A sanitary survey is a comprehensive evaluation of the water source, treatment facilities, operation and maintenance, and management of public water systems. It is intended to improve system safety and operation, and safeguard public health.

Enclosed is the water system's sanitary survey report with IHS' recommended actions to address deficiencies. EPA Region 10 will utilize the results of this report to identify significant and minor deficiencies and notify you of them in a separate letter.

By signing below, I am granting the IHS permission to send a copy of this letter, which summarizes the findings of the Sanitary Survey Form, to the Region 10 Environmental Protection Agency (EPA) Drinking Water Program. Feel free to call me with any questions, comments, or concerns regarding the assessment details.

Sincerely,

Concurrence

Laddie Folster

Indian Health Service

Tribal Utility Consultant

Water System Manager

Rov Spino

Date

Warm Springs Tribe

Enclosures: Sanitary Survey Form, Deficiencies and Recommendations

cc: Jenna Manheimer, Tribal Drinking Water Coordinator, EPA

Matty Haith, District Utility Consultant, Indian Health Service

Don Courtney, General Manager Public Utilities, Warm Springs Indian Reservation

Nancy Collins, EHS, Warm Springs Indian Reservation

Deficiencies and Recommendations

Page 2, Item 4: A sample tap is required after the chlorine is injected. This is important because there are a number of samples that must be taken after treatment as well as measurement of chlorine residuals entering the WST. Recommend installing sample tap. This Deficiency was not corrected from the April 24, 2014 Sanitary Survey.

Page 2, Item 6: The sanitary well cap is lacking a screened (24-mesh) vent, turned downward and a minimum 18-inches above the floor of the pumphouse. There is a plastic tube stuck into the hole where a threaded vent pipe is normally located. Installing a simple treaded pipe in this hole and raising it high enough to turn downward and covering it with a 24-mesh screen is a recommended solution. This Deficiency was not corrected from the April 24, 2014 Sanitary Survey.

Page 2, Item 7: The electrical wire entering the top of the well, enters a penetration through the sanitary well seal that is not sealed adequately to prevent insect entry. This deficiency needs to be corrected because it has been demonstrated insects will enter into the well and can die and fall into the well. Sealing this gap can be as simple as using a calking suitable for potable water or using a seal-tight flexible conduit. This Deficiency was not corrected from the April 24, 2014 Sanitary Survey.

<u>Page 3, Item 63</u>: Safety-No eye-washing provision was seen in the pumphouse in case of splash of the strong chlorine solution. Recommend installing an eye wash station.


<u>Page 4, Item 120</u>: Mr. Tohet indicated the distribution valves were not regularly exercised. Recommend that a valve exercise program be implemented.


Page 4, Item 121: Mr. Tohet indicated that he did not know if customer complaints were investigated.


Recommend that customer complaints be investigated and reports filed.

<u>Page 4, Item 124</u>: Mr. Tohet was not aware of a distribution flushing program. Recommend at least annually flushing the water mains in such a way as to eliminate sediments etc.

<u>Page 4, Item 126</u>: Mr. Tohet is not trained in recognizing cross connections. Recommend that the operator and perhaps other utility personnel attend a cross connection training course. Contact IHS for date to the next training.







Page 3 – Don Courtney– Confederated Tribes of Warm Springs

<u>Page 6, Item 165</u>: Non-sample taps (hose bibs) in the pumphouse need to be equipped with backflow devices such as a vacuum breaker. These are fitted directly to the hose bib and are relatively inexpensive at hardware or plumbing store.

Page 8, Item 216: Lack of a well head protection program.

Page 8, Item 217: CCRs are not distributed on a timely schedule every year.

Page 8, Item 218: Lack of a Master Plan for the Sidwalter CWS.

Page 8, Item 216: Lack of a Water Conservation Plan.

Spino Sidwalter Community Water System Sanitary Survey Includes: Warm Springs, Oregon 97761 Water Supply Address Oregon 97761 Water Supply Mailing Address Name of Water Supply Date of last survey PO Box 1209 System Managers First Name 4/24/2014 Surveyed by System Managers State System Managers Address System Managers Last Name Plant Location (if different from above) Water Supply City, State, Zip have reviewed all pages of the Sanitary Survey form # of Residential Connections System Type: (5) Pumps, PF, and Controls I. SITE VISIT INFORMATION # of Non-Residential Connections 4/25/2017 (1) GW Source Federal Government Warm Springs Reviewed with Surveyor I have reviewed all pages of the Sanitary Survey form 541-553-2324 System Managers Telephone System Managers City Water Supply Telephone Private 🗌 (6) Monitoring (7) Management/Operation Capacity (8) (2) Well Water Treatment Part A 🗷 Part B Water Sold To: Water Purchased Front: Native American Government Total Population Confederated Tribes of Warm Springs Reservation 135 State Government 1/20 11/2 n/a Indian Population Small rural CWS on the Warm Springs Reservation. Single well with a single WST. Sodium Hypo Warm Springs, Oregon 97761 Owner City, State, Zip Confederated Tribes of Warm Springs 1233 Veterans St used for disinfection. Name Name Owner Address Owner Name Surveyors Agency Indian Health Service Water System Classification Service Category
Community Water System

Non-trans Name Name Individuals present during inspection Comments A SAME SANDON AND THE COURSE AND SANDON SANDON AND SANDON Jason Tohet Laddie Folster Other Local PWS SWd , |**८** n/a n/a Mixed (Public/Private # of Storage Facilities Non-transient Non-community (8) Operator Compliance Combined Sources (3) Distribution SDWIS Classification; C Infiltration Gallery District Spokane Well Field SURVEY DATE 4/25/2017 Title Title Title Operator Tide IHS TUC Yes (4) Finished Water Storage # of GW Sources Transient Non-community (9) Consecutive Systems Other Lake ö 541-553-1161 Owner Telephone Seasonal: No PWS ID 104101101 River/Stream

Rev. November 2015

Official Form SS 1

Keep For Your File

Page

of,

ED_004384_00001933-00033

Official Form SS 1

Surveyed by: Survey Date Ladd Folster 4/25/2017	I.4. Individual home seepage pit (100 ft) I.5. Is a GWUDI determination necessary for this source?	☑ ☐ ☐ 13. Livestock (100 ft)		10. Pressure sewer line (100 ft)		HAVE THE FOLLOW	 Are conduitsand junction boxes scaled to prevent contaminants from entering the well casing? S. Is the source metered? 				3.	2. Does the casing extend a minimum of 18-inches above the final ground surface and/or 12-inches above the pump house floor or slab?	LES INC. IN A CINE. I. Is the well provided with a sanitary cap, vent, and seal that are properly installed?	SIGNIFICANT DEFICIENCY	Source of Potential Pollution None in Area Are static and pumping were	Confined Unconfined Unknown	Recharge Area	Scree	Well/Spring Yield (GPM) Pump Capacity (GPM)	Has well-log been submitted to EPA? YES 🗌 NO 🗌 Unknown 🗹	Disinfection		Physical Address No Address-See Lat Long Seasonal Operation Dates Start End	Source Name Sidwalter Well	2. GROUNDWATER SOURCES #1
Improper well vent. Lack of proper conduit penetration through well cap.	K		24. Venting	☑ ☐ ☐ 23. Lighting	ARE WELL HOUSE BUILDINGS CONSTRUCTED OR MAINTAINED TO PROVIDE:	22. Has a source water assessment been conducted for this source?	RECOMMENDATION	21. Is a pressure gauge or other means of measuring water level provided at the installation and is it maintained and working properly?	an approved air gap at a location prior to the first service connection? 20. Is standby or auxiliary power available?	S	18 	maintained and operating properly? If I, Is well site properly drained and protected from unauthorized entry?	YES NO N/A ONK	NEW TOWN TO THE TO	ared regularly? Are chemical contaminants source in	Well Head Protection Yes No W UNKNOWN YES NO W UNKNOWN UNKNOWN	3671	Grout Depth (ft) 25 Date Drilled 1/1/1985	Design Daily Production (GPD) 20,000		Sodium Hypochlarite	Treatment Methods		chase	SLIRVEY DATE PWS ID 4/25/2017 104101101

pipelines clearly labeled to identify the chemical they contain? 70. Have there been any interruptions in disinfaction in the past year? Comments:	Ifly accessible for servicing, repair and	### St. Are critical \$ ### St. How are the incomplete covered? ### St. How are the incomplete covered? ### St. How are the incomplete covered? ### St. How are the incomplete covered? ### St. Are chemical of disinfection on hand? ### St. Are chemical solutions of disinfectant in properly? ### washing device installed where strong acids ed? ### washing device installed where strong acids ed? ### washing device installed where strong acids ed? ### washing device installed where strong acids injection of the provided by a flow sensing devise so that I not continue when flow of the water stops? ### provided so the liquid chemical solutions in provided so the liquid chemical solutio	Gas Sodium hypochlorite (12 1/2%) Calcium hypochlorite Bleach S 1/4 % Ozone UV light Chlorine dioxide Other Ozone UV light Chlorine dioxide Other Ozone UV light Chlorine dioxide Other Ozone UV light Chlorine dioxide Other Ozone UV light Chlorine dioxide Other Ozone UV light Chlorine dioxide Other Ozone UV light Chlorine dioxide Other Ozone UV light Chlorine dioxide Other Ozone UV light Chlorine dioxide Other Ozone UV light UV light Chlorine dioxide Other Ozone UV light UV light Chlorine dioxide Other Ozone UV light UV light Chlorine dioxide Other Ozone UV light UV light Chlorine dioxide Other Ozone UV light UV light Chlorine dioxide Other Ozone UV light UV light Chlorine dioxide Other Ozone UV light UV light Chlorine dioxide Other Ozone UV light UV light Chlorine dioxide Other Ozone UV light UV light Chlorine dioxide Other Ozone UV light UV light Chlorine dioxide Other Ozone UV light UV light Chlorine dioxide Other Ozone UV light UV light Chlorine dioxide Other Ozone UV light UV light UV light Chlorine dioxide Other Ozone UV light UV light UV light Ozone UV light UV light UV light Ozone UV light UV light UV light Ozone UV light UV light UV light Ozone UV light UV light UV light Ozone UV light UV light UV light Ozone UV light UV light UV light Ozone UV light U	Physical Address I Share treated by station 2 Physical See Lat/Long Schematic of plant readily available and up to date? Yes No Check all disinfection types used:
	adily accessible for servi- his treatment facility since I is stored or handled, are fy the chemical they conto in disinfection in the pass	covered? isinfection on hand? etermine chemical feed re available and operational conduct monitoring of dis conduct monitoring of device installed when the distribution of the continue when flow of the distribution feeders into the weather of rubber gloves, a distribution of the controlled for each operation.	m hypochlorite Bleach 5 1/4 % Alorine dioxide Other Other (C) condition? fully labeled to include chemical name ASI/NSF certification?	4/25/2017 104101101 Address 2 Schematic of plant readily available and up to date? Yes No

ED_004384_00001933-00035

6. DISTRIBUTION	32	SURVEY DATE PWSID 104101101
	AC PE C CI/DI	NO NATE MINORDEFICIENCE
Distribution line (Diameter and type)	Service line (Diameter and type)	119. Are accurate O and M records being maintained (check records)?
1. 4" PVC	1. <u>1"HDPE</u>	
'n	Þ	121. Are customer complaints and investigation reports kept?
How many service lines are metered?	Number of Fire Hydrants (types if known)	122. Are all automatic air relief valves equipped with a means of backflow protection?
36 out of 36	1. 2	123. Are ARV's turned down, screened, and protected from cross connection?
	, jej	☐ ☑ ☐ ☐ 124. Is there a routine main and dead-end water flushing program?
INVJERNAR		≪ □ 125.
YES NO N/A UNK		126. Is the operator trained in cross connection control?
	Are there hydrants or adequate blow-offs to flush all dead-end on the system?	127. Are proper procedures followed for disinfection of new construction or repairs?
In the distribution system? In the distribution system?	Are disinfectant residual measurements being made and recorded at the entry point of the distribution system?	
✓ ☐ ☐ 112. Is there a disinfectar distribution system?	Is there a disinfectant residual of at least 0.2 mg/l at the entry point of the distribution system?	RECOMMENDATION
✓ ☐ ☐ 113. Is a detectable free c distribution system?	Is a detectable free chlorine residual being maintained throughout the distribution system?	
✓ ☐ ☐ 114. Are proper residual (DPD)?	Are proper residual test kits available and well-stocked with reagents (DPD)?	
☐ ☐ I15.	Is the PWS able to maintain a minimum pressure of twenty (20) psi throughout the distribution system (including fire flow)?	☐ ☑ ☐ ☐ 131. Was asbestos/coment pipe used in the system?
the survey?	Is the system protected from obvious cross connection observed during the survey?	
☐ ☐ ☐ 117. Is there a requireme devices?	Is there a requirement for annual testing of installed backflow prevention devices?	
118. Is there sufficient or point in use? If not,	Is there sufficient contact time between the disinfection point and first point in use? If not, is the system performing triggered monitoring?	
Comments		
Surveyed by: Survey Date Ladd Folster 4/25/2017	117	.
Rev. November 2015	Official Form SS 1	omn SS ! Keep For Your File Page of

Official Form SS 1

Keep For Your File

serves as spiaso pad. Aunchoning seased happer valve at terminus.	by: Survey Date ster 4/25/2017	Surveyed by: Ladd Folster
	Yes 🕢 No 🔲 Line Type?	***************************************
Number and tank(s) in gallon	148. Is storage structure lined?	S
	147. ls there a	口 弘
What is the make and model of the tanks?	3333333	
161. Is there a drain line on each tank?		
160. Are the interior and/or exterior surfaces in good condition?	145. Does the overflow have a splash pad?	S
	144. Is the storage structure secured from unauthorized access?	<u>s</u>
RECOMMENDATION RECOMMENDATION	143. Do all vents open downward and are they fitted with a 4-mesh non-corrodible screen?	<u>s</u>
glass A drain	142. Is the storage structure protected against flooding?	
159. Do all non-bladder hydro pneumatic tank(s) have the following? Check all that apply:	l4]. Can the storage structure be isolated from the system for repairs or cleaning?	<u> </u>
in the past 5 years?		
] [
NON-BLADDER 157 Is an oil-less air compressor in berries for the hydrogeneous reasons tends	provide provid	
156. Can the tank(s) be isolated with a shut-off valve for repairs or replacement	the diameter of the water outlet above the ground or storage structure surface?	
BLADDER AND NON-BLADDER	downward or covered, screened and terminated a minimum of 2 times	
	;	
155. Is the pressure tank being inspected?	137. Are access manhole openings for the storage structure 4 inches or greater above the reservoir roof surface, with a lid 2 inches	S
154. Is there a pressure gauge and pressure operated start-stop control?	practical, provided with a metal screen or flapper valve?	
	136. Is an overflow provided that discharges to daylight in a way that will	S
[] [] [] 152. Is/kye tank(s) located above normal ground surface and completely housed?	135. Is the storage structure safely accessible to inspector?	S
Can the hydropneumatic tank(s) be isolated from the system, permitting permitting	134. Is the storage structure structurally sound?	S
HYDROPNEUMATIC SYSTEM	133. Is the storage structure clean and free from contamination?	S
YES NO NIA UNK	IN IN ONE. 132. Is treated water storage covered or enclosed?	
	3314	
Total design capacity Date last: Cleaned Inspected	s of supply 3 Date last: Cleaned inspected	Lotal days of supply
Date in Service Type of material Volume (gal)	NK Type of mate	Date in service
Typeof hydropneumatic system: Non-bladder 🗌 Bladder 🗌	control Cathodic Storage type Standpipe	Corrosion control
Ressure tank name Physical location:	Storage structure name Sidwalter Physical location:	Storage stru
al) 209,000 SHRVEY DATE DWSID 4/25/2017 104101101	7. FINISHED WATER STORAGE #1 Total Storage Capacity (gal)	
~	PUBLIC WAITER SYSTEM SANITARY SURVE	

Rev. November 2015

Official Form SS 1

Keep For Your File

Page D of B

PORTLAND AREA INDIAN HEALTH SERVICE

PUBLIC WATER SYSTEM SANITARY SURVEY	SANITARY SURVEY
8. PUMPS, PUMP FACILITIES, AND CONTROLS #1	SURVEY DATE PWSID 4/25/2017 104101101
ource Treated By Station Physical Address	Comments
idwalter Well inside Sidwalter PH SIGNIFICANT FIRM OF THE SIDWALE SID	Some signs of rodent or small aninmal infestation. Need to be addressed or kept clean as well as possible. Three Phase power for the well pump is through a Rotary Generator.
YES NO N/A UNK 162. Is adequate ventilation provided in the pump house for dissipation of excess heat and moisture from the equipment?	
✓ ☐ ☐ 163. Is the building in good structural condition?	
🗹 🗀 🗀 164. Is the building orderly and clean?	
AIMOR DISHCIPACE	
PUMPHOUSE 165 Are all non-earnile tans installed in the namen house equipmed with an	
166. Is the pump house protected from flooding, have adequate drainage and is the floor surface at least six (6) inches above the final ground surface?	
□ ⊠ □ 167.	
168. Is the pump house protected from unauthorized personnel?	
[] [] [] [] [] [] [] [] [] []	
☐ ☑ ☐ 170. Are pump records maintained?	
171. Are all pumps capable of providing the max pumping demand of the system?	
172. Does the pump(s) cycle excessively?	
[] [] [] [] [] [] [] [] [] []	
☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐	
☐ 😾 ☐ 175. Is a water pressure relief valve installed where the pump is directly	
176. Is the pump house kept clean and in good repairs?	
In the pump house have adequate lighting throughout?	
ump type: Submersible 🗹 Centrifugal Variable Frequency Drive (VFD)	
inklin Pump mode	
ump Controls have: Float switch Run Hour Meter Pump Protector Pressure Switch Lead/Lag Manual Sequencer Controls Other	. š
What are the most frequent Complaints?	
urveyed by: Survey Date 4/25/2017	

Surveyed by: < < < < < KKKK SEA Is the system in monitoring compliance for the following parameters: Sidwalter Community Water System Name of Water Supply Comments < Ladd Folster O N/A UNK 9. MONITORING 182. 198. Are HAA5 samples taken at location of maximum residence time 197. Are TTHM samples taken at location of maximum residence tim 196. Is all required monitoring current? 195. Are copies of public notices available? 194. Maximum Residual Disinfectant level 192. 191. Asbestos 190. Lead Copper (# of sites) 189. Coliform 188. Radium 228/226 187. Bromate ozone (if required) 186. Fluoride 185. Turbidity 184. CT Value (for systems avoiding triggered monitoring 183. Arsenic 181. VOC 180. Gross Alpha Screen Uranium 179. Inorganics (including nitrates) 193. HAA5s 178. Nitrate MHTT SOC Survey Date IN THE DISTRIBUTION AT THE ENTRY POINT 4/25/2017 Confederated Tribes of Warm Springs Reservation Tribe Are the following records maintained on-site or location nearby: 202. Chemical Analysis 208. Are daily free/total chlorine residual taken? 207. Daily free chlorine residuals are not kept on site 206. Copies of public notices 205. Reports of variance or exemption 204. Copies of past sanitary survey 203. Violation records 201. Bacteriological Analysis SURVEY DATE 4/25/2017 104101101

Rev. November 2015

Official Form SS 1

Keep For Your File

ED_004384_00001933-00039

Ladd Folster Surveyed by: **ष्ट ष ष ष S S** < < * दददद < 223. Does the Water System have a water facilities inventory? 223. Does the Water System have a service area and facility map? 221. 218. Does the Water System have a current master plan? 217. Are consumer confidence reports sent to users each year? 216. Does the Water System have a Wellhead Protection Program? 215. Does the system have more than 4 violations in the past two years? 214. Is the Water System in compliance? 213. Does the Water System have a Cross-Connection Control Program? 212. Does the water system have an emergency response plan? 211. Does the system have written standard operating protocol for other operators? 210. Does the Water System have an operation and maintenance manual? 209. Is the Manager/Contractor certified at appropriate level? 228. 227. Is there a clear plan of organization and control among the people 226. Does the PWS have a governing body or board of directors? 225. Has a capacity assessment been completed? 222. Does the Water System have an Operating Budget? 220. 219. Does the master plan include a water conservation plan? ☐ Monthly 10. MANAGEMENT/OPERATION CAPACITY Never Generator, manual switchover Portable with transfer switch Generator, automatic switchover Does the Water System have emergency power? Is there a written Water Quality Monitoring site plan/program available What year was the master plan completed? responsible for management and operation of the Water System? for review? Survey Date RECOMMENDATION 4/25/2017 Frequency of testing generator: Quarterly ☐ Annually Other Transfer switch only ☐ Infrequently Comments: CCR Violations for 2001, 2012, 2013 Roy Spino プログラ Operator(s) Name Jason Tohet 229. Operator Qualification or Certification YES YES Are any of the deficiencies listed below noted elsewhere in this survey? < < 8. OPERATOR COMPLIANCE NO N/A NO N/A d SNK UNK 232 236 233 237 235 234 231. Is a properly certified operator available at all times? 230. Are Operators certified at the appropriate level? V-081377 Cert. OR R Ş S R <u>Z C</u> 9. OTHER Cert. Level E 2 Meets System Requirements Yes Yes Issued Date 104101101 12/31/17 Date Expires

Rev. November 2015

Official Form SS 1

Keep For Your File

Page

ED_004384_00001933-00040